

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8

	230
OPERATING OUTPUT VALUE Vb	PERCENTAGE R MACHITUDE OF COMMANDED FORCE MAXIMUM VALUE THAT CAN BE COMMANDED
0	1
1	<u>126</u> 127
126	1 127
127	0
128	1 128
254	<u>127</u> 128
255	1 .

FIG. 9

OPERATING OUTPUT VALUE Va	PERCENTAGE R MAGNITUDE OF COMMANDED FORCE MAXIMUM VALUE THAT CAN BE COMMANDED
0	1
1	<u>1</u> 255
254	<u>254</u> 255
255	1

FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27